

Area of Damaged
Scaffolding

Figure 1 – Reactors with Damaged Scaffolding




Figure 2 – Reactor Effluent Pipe Rupture



Panel

Figure 3 – External Temperature Panel Location



Figure 4 – Effluent Pipe Rupture Seen From Back Side of Reactor




Figure 5 – Ruptured Effluent Pipe After Removal